Work	Order	ID	58980
------	-------	----	-------

Page 1

May 20, 2010 1:38:24 PM

Item ID:

D4064-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Mounting Lug

Start Date:

Required Date: 5/28/10

5/20/10

QC:

Start Qty: 20.00 Req'd Qty: 20.00

Cust Item ID:

Customer:





Reference:

Approvals:

Process Plan:

Α

Date: Date: Tooling:

SPC (Y/N):

Date: Date:

Start

Stop

Sequence ID/ Work Center ID Operation Description

Revision Nbr

Set Up/ Run Hours

Draw Number Draw Plan Rev. Code

Accept Qty

Reject Qty

Run

Reject Number

Insp. Stamp

D4064 100

Draw Nbr

Waterjet

FLOW CNC Waterjet

Memo

Cut as per Dwg DWG REV: PROG REV:

0.00

0.00

1B 10-5-26

110

Quality Control

QC2- Inspect parts off machine FAI/FAIB

DEBURR IF REQUIRED

0.00

Memo

0.00

H3 10-5-26

Dart	Aer	ost	pace	Ltd

W/O:			W	ORK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CH	ANGE	E	Ву	Date C	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cat	egory:	NCR:	Yes N	lo DQA:_		_ Date: _	
	R	esolution:	Dispositi	on:	QA: N	/C Clo	sed:		Date:	
NCR:			WORK ORE	DER NON-CONFORM	ANCE (NCR)				
DATE	STEP	Description of NC			ection B		Verificati	ion	Approval	Approvai
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section (Chief Eng	QC Inspector
				v.				1		
4										
	·									
							•			
										-
			· 1							ľ

May 20, 2010 1:38:25 PM

Item ID:

D4064-041

Accept

Setup Start

Stop



Revision ID:

Item Name: Mounting Lug

Required Date: 5/28/10

Start Date:

5/20/10

Start Qty: 20.00

Req'd Qty: 20.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: Date: Tooling:

MILL RADS, DRILL HOLES AS PER DWG

GRIND RAD .060"-.100" BY HAND

QC: Date: SPC(Y/N):

Date:

Date:

Start Run

Stop



Sequence ID/ **Work Center ID**

130

Mill Conv

Conventional Milling Machine

Operation Description Set Up/

Run Hours 0.00

Draw Number

10/06/02

Draw Plan Rev. Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

QC2- Inspect parts off machine FAI/FAIB

0.00

0.00

Quality Control

Memo

Memo

0.00 \$ 20/06/02

150

140

Quality Control

Memo

QC8- Inspect parts - second check

/m/10.00.08

Da	rt /	Aer	OS	pac	е	Ltd
----	------	-----	----	-----	---	-----

W/O:		WORK ORDER CHANGES									
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву		Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
											
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Y	es No	DQA:	Date: _			
	Re	esolution:	Disposition	1:	_ QA: N/C	Close	ed:	Date: _			
NCR:			WORK ORDI	R NON-CONFORM	ANCE (N	CR)					
DATE	STEP	Description of NC			ion B		Verification	Approval	Approval		
	0.2	Section A	Initial Chief Eng	Action Description Chief Eng	Siç D	ın & ate	Section C	Chief Eng	QC Inspector		
				•		-					
	-										
				·				· · · · · · · · · · · · · · · · · · ·			
					İ						

May 20, 2010 1:38:26 PM

Item ID:

D4064-041

Accept

Setup Start

Stop



Revision ID:

Item Name: Mounting Lug

Start Date: 5/20/10 Required Date: 5/28/10 **Start Qty: 20.00**

Reg'd Oty: 20.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____ Date: ____ Tooling:

Date:

Run

Start

Stop

Date:

SPC (Y/N):

Date:

Operation Description

Chemical Conversion Coat per QSI005 4.1

Set Up/ **Run Hours** Draw Number

Draw Plan Rev. Code

Accept Qty

Reject Qty

Reject Insp. Number

Stamp

Work Center ID 160

HandFinish

Sequence ID/

Hand Finishing

Memo

0.00 M 10/06/09

0.00 =) 94 10/06/09

170

Powdercoat Powder Coating M114841

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

START: 10: 15A4 Memo TCMP: 320%

FIN: 10:45 Ac

QC3- Inspect Part Finish

0.00

180

Quality Control

Memo

0.00

W/O:		WORK ORDER CHANGES							
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date Qt	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No		PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA: _	Date: _		
	R	esolution:	Disposit	ion:	QA: N/C CI	osed:	Date: _		
NCR:		V	WORK OR	DER NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC		Corrective Action Section		- Verificatio	n Approval	Approval	
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector	
							·		
								-	
	:								
						,			
 									
					ļ				
				·					

Work Order ID 58980

May 20, 2010 1:38:26 PM



Page 4

Item ID:

D4064-041

Accept

Accept

Qty

Setup Start

Stop



Revision ID:

Start Date:

Item Name: Mounting Lug

Required Date: 5/28/10

5/20/10

Start Qty: 20.00

Operation

Description

Req'd Qty: 20.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

ASSEMBLE GROMMETS AS PER DWG

Tooling:

Date:

Draw

Number

Run

Start



Date:_____ SPC (Y/N):

Date:

Draw

Rev.

Plan

Code

Stop



Insp.

Stamp

Reject

Number

Sequence ID/ **Work Center ID**

190

HandFinish Hand Finishing

Memo

Memo

Set Up/ **Run Hours**

0.00

0.00

Reject

Qty

200

Quality Control

QC5- Inspect part completeness to step on W/O

Identify as per dwg & Stock Location

Packaging

Memo

Packaging

210

0.00

W/O:			V	VORK ORD	ER CHANG	iES					
DATE	STEP	PRO	OCEDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									·		
Part No	;	PAR #:	Fault Ca	tegory:	· .	_ NCR	: Yes I	No DQA:		_ Date:	
	R	esolution:	Disposit	ion:		QA:	N/C Clo	sed:		Date:	·
NCR:		1	WORK OR	DER NON-	CONFORM	ANCE	(NCR)			
DATE	STEP	Description of NC		Corrective		tion B	0:	Verifica	tion	Approval	Approvai
		Section A	Initial Chief Eng		n Description Chief Eng		Sign & Date	Section	С	Chief Eng	QC Inspector
	ı										
				·							
	1	`									Ì

Work Order ID 58980

May 20, 2010 1:38:26 PM



Page 5

Item ID:

D4064-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Mounting Lug

Start Date: 5/20/10 Required Date: 5/28/10

QC:

Start Qty: 20.00

Req'd Qty: 20.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Operation

Description

Date:

Date:_____

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Run

Start

Stop



Sequence ID/

Work Center ID

220

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Draw Number Draw Rev.

Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

Quality Control

ROSITIVE RECALL

RELEASE

W/O:	1		V	VORK ORDER CH	ANGES					
DATE	STEP	PRO	CEDURE CH	HANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						<u> </u>				
Part No	:	PAR #:	Fault Ca	tegory:	NC	R: Yes	No DQ	A:	Date:	
	Re	esolution:							Date:	
NCR:		V	VORK OR	DER NON-CONFO	RMANCE	(NCR)			
DATE	STEP	Description of NC	Initial	Corrective Action Action Descrip	Section B	Sign &		cation	Approval	Approval
		Section A	Chief Eng	Chief Eng		Date	Secti	on C	Chief Eng	QC Inspector
										-
						-				
					•					
								-		

Picklist Print

May 20, 2010 1:38:23 PM

Work Order ID: 58980

Parent Item:

Comments:

D4064-041

Parent Item Name: Mounting Lug

IPP REV:A NEW ISSUE 10-03-01 JLM VERIFIED BY:EC

Start Date: 5/20/10

Required Date: 5/28/10

Page 1

Start Qty: 20.00

Required Qty: 20.00

1810-5-26

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	Date Issued	Status
M6061T6B0.750X06.00	,	Purchased	No		100	f	53.0800	0.35	7.	- 	



6061T6 BAR .750 X 6.00

Location Loc Code Loc Qty MAT03 53.08 112567 53.08 123.0000

MS35489-93

Purchased

No

190 Each

Location Loc Qty Loc Code ST293 100 114341 100 ST295 23 114108 23

GROMMET

W/O:			WC	ORK ORDER CHAN	GES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,							
					·				
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	s No DQ	A:	Date: _	L
	R	esolution:	Disposition	າ:	QA: N/C	Closed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NO	R)			
DATE	STEP	Description of NC			ction B	Verific	cation	Approval	Approval
	O I E I	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Secti	ion C	Chief Eng	QC Inspector
		,							
		,							
						,			
					-				
	T.	1	1 1		ı	4		l	I

DART AEROSPACE LTD	Work Order:	58480
Description: Lug	Part Number:	D4064-1
Inspection Dwg: D4064 Rev: A		Page 1 of 1

	FIRST	ARTICLE IN	ISPECTION	ON CHE	CKLIST		
	x	First Artic	ele	Proto	type		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Co	mments
4.45	+/-0.030	4.448	*				
0.306	+/-0.010	1306	4				
2.960	+/-0.010	2.958	بر				
0.735	+/-0.010	737	>				
0.241	+/-0.010	234	¥				
0.750	+/-0.010		ý				
2.56	±.030	2.56					
3-100	± 010	3, 100					
6251	+.006	(A) 15-8	 	-			
a ut?	L,006	0,456	 				
			-				
,							
leasured by:	de	Audited by:			Prototype A	pproval:	N/A
	0-5-96	Date:	10.	06-0		Date:	N/A
	Change				Revis	ed by	Арргоуе

Rev	Date	Change	Revised	þy		Apr	3 00	ved
Α	10.04.01	New Issue	KJ	Φ	7	//		7
				TC	\mathcal{I}^{-}			,



